

SITE INSPECTION REVIEW FORMSITE NAME: GAF Corporation

ALIASES: _____

SITE I.D.#: NJD002185973

<u>ITEM</u>	<u>COMPLETE</u> <u>YES</u>	<u>?</u> <u>NO*</u>
SITE LOCATION (INCLUDING MAP)	<u>✓</u>	<u> </u>
SITE BACKGROUND	<u>✓</u>	<u> </u>
ENVIRONMENTAL SETTING (GEOLOGY, HYDROLOGY, METEOROLOGY, ECOLOGY + LAND USE)	<u>✓</u>	<u> </u>
WASTE DESCRIPTION (PRESENCE + CONDITION OF WASTE + WASTE MANAGEMENT UNITS)	<u>✓</u>	<u> </u>
LABORATORY RESULTS (CORRELATED TO SAMPLE LOCATION MAP)	<u>✓</u>	<u> </u>
HRS PRE - SCORE (PRELIMINARY + PROJECTED)	<u>✓</u>	<u> </u>
POTENTIAL FOR DIRECT CONTACT	<u>✓</u>	<u> </u>
CONCLUSIONS + RECOMMENDATIONS	<u>✓</u>	<u> </u>
REFERENCES	<u>✓</u>	<u> </u>

HRS PRE-SCORE: PRELIMINARY SCORE = 25.88
PROJECTED SCORE = 41.57

COMMENTS:

This site has a chemical manufacturing history dating back to 1919. There is documented soil and groundwater contamination from the numerous operations of this 70 year period. There have been releases as well to the surface water (Piles Creek), and a wetland 2 miles away (Pralls Island) is a potential contaminant receptor. MEDIUM PRIORITY SITE - ^{targets are} not very high. The projected air pathway score should not have been computed. It inflates the overall SM (projected) from 26.79 to 41.57.

DAF, in an ACO with NJDEP (1989), has agreed to conduct an RI/FS, and to design and implement remedial action alternatives.

REVIEWED BY: LARRY TANNENBAUM

DATE: FEB. 15, 1990

*IF ANY ITEM IS LACKING INFORMATION PLEASE DESCRIBE IN COMMENTS